DHV TESTREPORT LTF 2009

SKYWALK CHILI2 XS

Type designation Skywalk Chili2 XS Type test reference no DHV GS-01-1898-10 Holder of certification Skywalk GmbH & Co. KG

Manufacturer Skywalk GmbH & Co. KG

Classification B

Winch towing Yes

Number of seats min / max 1 / 1

Accelerator Yes

Trimmers No



BEHAVIOUR AT MIN WEIGHT IN FLIGHT (60KG)

Test pilots Gudrun Öchsl





		Beni Stocker
1-51-1: /1-155	Δ	
Inflation/take-off	A	A
	Smooth, easy and constant rising	Smooth, easy and constant rising
Special take off technique required	I No	No
Landing	А	А
Special landing technique required	l No	No
Speeds in straight flight	Α	A
Trim speed more than 30 km/h	Yes	Yes
Speed range using the controls larger than 10 km/h		Yes
	Less than 25 km/h	Less than 25 km/h
Control movement	Α	A
Symmetric control pressure	Increasing	Increasing
Symmetric control trave	Greater than 55 cm	Greater than 60 cm
Pitch stability exiting accelerated flight	Α	Α
Dive forward angle on exit	Dive forward less than 30°	Dive forward less than 30°
Collapse occurs	No No	No
Pitch stability operating controls during	Δ	A
accelerated flight		
Collapse occurs	s No	No
Roll stability and damping	Α	Α
Oscillations	Reducing	Reducing
	1	
Stability in gentle spirals	Α	Α
Tendency to return to straight flight	Spontaneous exit	Spontaneous exit
^		
Behaviour in a steeply banked turn 🄼 🗀	Α	В
Sink rate after two turns	Up to 12 m/s	More than 14 m/s
Symmetric front collapse	Α	В
Entry	Rocking back less than 45°	Rocking back less than 45°
Recovery	Spontaneous in less than 3 s	Spontaneous in 3 s to 5 s
Dive forward angle on exit	Dive forward 0° to 30°	Dive forward 0° to 30°
	Entering a turn of less than 90°	Entering a turn of less than 90°
Cascade occurs	s No	No
Symmetric front collapse in accelerated flight	В	В
	Rocking back less than 45°	Rocking back less than 45°
	Spontaneous in 3 s to 5 s	Spontaneous in 3 s to 5 s
Dive forward angle on exit	•	Dive forward 0° to 30°
	Entering a turn of less than 90°	Entering a turn of less than 90°
Cascade occurs	-	No
ouscade occurs		110

Exiting deep stall (parachutal stall)	A	A
Deep stall achieved	A	Yes
·	Spontaneous in less than 3 s	Spontaneous in less than 3 s
Dive forward angle on exit		Dive forward 0° to 30°
	Changing course less than 45°	Changing course less than 45°
Cascade occurs	3 3	No
Cascade occurs	NO .	NO
High angle of attack recovery	Λ	Δ.
High angle of attack recovery	Α	Α
	Spontaneous in less than 3 s	Spontaneous in less than 3 s
Cascade occurs	No	No
:	:	
Recovery from a developed full stall	Α	В
Dive forward angle on exit	Dive forward 0° to 30°	Dive forward 30° to 60°
Collapse	No collapse	No collapse
Cascade occurs (other than collapses)	No	No
Rocking back	Less than 45°	Less than 45°
Line tension	Most lines tight	Most lines tight
Asymmetric collapse 45-50%	Α	Α
Change of course until re-inflation	Less than 90°	Less than 90°
Maximum dive forward or roll angle		Dive or roll angle 15° to 45°
Re-inflation behaviour	-	Spontaneous re-inflation
Total change of course		Less than 360°
Collapse on the opposite side occurs		No
Twist occurs		No
Cascade occurs		No No
Cascage occurs	INO	INO
Acummetric colleges 70, 750/	D	D
Asymmetric collapse 70-75%	B	B
Change of course until re-inflation		90° to 180°
Maximum dive forward or roll angle		Dive or roll angle 15° to 45°
Re-inflation behaviour		Spontaneous re-inflation
Total change of course		Less than 360°
Collapse on the opposite side occurs		No
Twist occurs		No
Cascade occurs	No	No
		:
Asymmetric collapse 45-50% in	Α	A
accelerated flight		
Change of course until re-inflation		Less than 90°
Maximum dive forward or roll angle	Dive or roll angle 15° to 45°	Dive or roll angle 15° to 45°
Re-inflation behaviour	Spontaneous re-inflation	Spontaneous re-inflation
Total change of course	Less than 360°	Less than 360°
Collapse on the opposite side occurs	No	No
Twist occurs	No	No
Cascade occurs	No	No
Asymmetric collapse 70-75% in	В	В
accelerated flight	Ь	Ь
Change of course until re-inflation	90° to 180°	90° to 180°
Maximum dive forward or roll angle	Dive or roll angle 15° to 45°	Dive or roll angle 15° to 45°
Re-inflation behaviour	Spontaneous re-inflation	Spontaneous re-inflation
Total change of course	Less than 360°	Less than 360°
Collapse on the opposite side occurs	No	No
Twist occurs	No	No
Cascade occurs	No	No
Directional control with a maintained	۸	۸
asymmetric collapse	Α	Α
Able to keep course	Yes	Yes
180° turn away from the collapsed side possible	Yes	Yes
in 10 s		
Amount of control range between turn and stall		More than 50 % of the symmetric
or spin	uavel	control travel
Tains and a six to the	Α	Δ.
Trim speed spin tendency	A	A
Spin occurs	No	No
Low speed spin tendency	Α	Α
Spin occurs	No	No
Recovery from a developed spin	Α	Α
Spin rotation angle after release	Stops spinning in less than 90°	Stops spinning in less than 90°
Cascade occurs	No	No
B-line stall	А	А
Change of course before release	Changing course less than 45°	Changing course less than 45°
	Remains stable with straight span	Remains stable with straight span
	Spontaneous in less than 3 s	Spontaneous in less than 3 s
Dive forward angle on exit		Dive forward 0° to 30°
Cascade occurs		No
Sussuad Steam's	·	
Big ears	В	A
	i	Dedicated controls
J .	Dedicated controls	
Behaviour during big ears	Stable Hight	Stable flight

Recovery Recovery through pilot action in less than a Spontaneous in less than 3 s further 3 s Dive forward angle on exit Dive forward 0° to 30° Dive forward 0° to 30° Big ears in accelerated flight Entry procedure Dedicated controls Dedicated controls Behaviour during big ears Stable flight Stable flight **Recovery** Recovery through pilot action in less than a Spontaneous in less than 3 s further 3 s Dive forward angle on exit Dive forward 0° to 30° Dive forward 0° to 30° Behaviour immediately after releasing the Stable flight accelerator while maintaining big ears Stable flight Α Behaviour exiting a steep spiral Tendency to return to straight flight Spontaneous exit Spontaneous exit Turn angle to recover normal flight Less than 720°, spontaneous recovery Less than 720°, spontaneous recovery Sink rate when evaluating spiral stability [m/s] 14 14 Alternative means of directional control A Α 180° turn achievable in 20 s Yes Yes Stall or spin occurs No No Any other flight procedure and/or configuration described in the user's manual

No other flight procedure or configuration described in the user's manual

by jursaconsulting

